



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 40-42	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 40-42 (same as felled tree)	434214.04	385290.55	Corylus colurna	434214.13	385290.42
adj hotel, 2nd tree from top/Kenwood Rd	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge OPPOSITE 1-3 (same as felled tree)	434137.97	385480.13	Corylus colurna	434138.34	385479.96
o/s 1 (3rd tree from junc Kenwood rd), alongside driveway for Kenwood Knoll	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Betula ermanii - Plant in new 800 pit at side of driveway for 1, (same as felled tree)	434146.73	385483.96	Betula ermanii	434146.78	385483.16
o/s 58	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 58 (same as felled tree)	434246.19	385209.29	Corylus colurna	434246.47	385209.26
o/s 9	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800 pit 3m away from driveway for 9, (same as felled tree)	434156.02	385461.07	Liquidambar styraciflua 'Worpl	434156.21	385461
o/s 11, just before junction with Kenbourne Rd	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Betula ermanii - Plant in new 800 pit 3m below driveway for 11, (same as felled tree)	434165.51	385436.66	Betula ermanii	434165.47	385436.89
o/s 56	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 56 (same as felled tree)	434241.36	385220.98	Corylus colurna	434241.15	385221.13
o/s 30	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 30 (same as felled tree)	434194.66	385338.44	Corylus colurna	434194.46	385338.52
o/s 19	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Betula ermanii - Plant in new 800 pit o/s 19, (same as felled tree)	434189.16	385378.02	Betula ermanii	434189.02	385378.76

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 50	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 50 (same as felled tree)	434231.36	385246.74	Corylus colurna	434231.83	385246.85
o/s 24	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 24 (same as felled tree)	434186.02	385361.74	Corylus colurna	434185.99	385361.82
o/s 14	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 14 (same as felled tree)	434170.42	385398.95	Corylus colurna	434170.41	385398.73
o/s 48	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 48 (same as felled tree)	434227.97	385254.79	Corylus colurna	434227.9	385254.87
o/s 12	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 12 (same as felled tree)	434165.6	385411.11	Corylus colurna	434165.72	385411.13
o/s 72	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 72 (same as felled tree)	434275.51	385135.64	Corylus colurna	434275.45	385135.64
o/s 70	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 70 (same as felled tree)	434269.83	385148.95	Corylus colurna	434269.8	385148.98
o/s 44	RUNDLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in verge o/s 44 (same as felled tree)	434218.31	385277.76	Corylus colurna	434218.37	385277.86